



BILL RICHARDSON  
Governor  
DIANE DENISH  
Lieutenant Governor

NEW MEXICO  
ENVIRONMENT DEPARTMENT

*Ground Water Quality Bureau*

1190 St. Francis Drive, P. O. Box 5469  
Santa Fe, NM 87502-5469  
Phone (505) 827-2900 Fax (505) 827-2965  
www.nmenv.state.nm.us



RON CURRY  
Secretary  
JON GOLDSTEIN  
Deputy Secretary

**Memorandum**

**To:** LaDonna Turner, Site Assessment Manager  
Technical and Enforcement Branch  
U.S. Environmental Protection Agency, Region 6

**From:** Dana Bahar, Manager, Superfund Oversight Section  
Ground Water Quality Bureau, New Mexico Environment Department.

**Date:** September 10, 2009

**Subject:** Pre-CERCLIS Screening Assessment of Isabella Mine, McKinley  
County, New Mexico: Further action under CERCLA recommended

|                  |                |              |            |               |          |                 |                |                  |                 |
|------------------|----------------|--------------|------------|---------------|----------|-----------------|----------------|------------------|-----------------|
| <b>Site name</b> | Isabella Mine  | <b>State</b> | New Mexico | <b>County</b> | McKinley | <b>Latitude</b> | 35° 22' 49.19" | <b>Longitude</b> | 108° 10' 10.00" |
| <b>City</b>      | not applicable |              |            |               |          |                 |                |                  |                 |
| <b>County</b>    | McKinley       |              |            |               |          |                 |                |                  |                 |
| <b>Latitude</b>  | 35° 22' 49.19" |              |            |               |          |                 |                |                  |                 |

**Site physical description:** The Isabella Mine is located on Navajo land. It consists of one open shaft that are approximately 0.06 miles apart. The mine is located approximately 0.6 miles south of the Rio Algom. The minesite is comprised of several piles of waste material. The waste material piles and barren area with elevated radioactivity; these are located in or near an arroyo. The waste material piles and barren areas with elevated radioactivity and an unfenced open shaft. This area is located at the base of an escarpment, along a roadway that has become a drainage.

**Site identification:** Potential alluvial ground water contamination within the Grants Mineral Belt was identified because background standards established for the contaminants of concern for ongoing remedial action associated with the Homestake Mining Company NPL site (CERCLIS NMD0007860935) are generally higher than Maximum Contaminant Levels (MCLs). NMED conducted sampling of private residential wells in subdivisions located in the vicinity of the HMC site, and found that the majority had one or more contaminant concentrations exceeding MCLs.

**Site summary:** Observations made during NMED's Site reconnaissance are shown on the accompanying figures. The barren area in the southern portion has radioactivity of 741 counts per second (cps; background assumed to be in the range of 10 to 40 cps from data collected at nearby sites); the waste material bordering and within the arroyo have slightly elevated radioactivity (highest reading during reconnaissance=104 cps). The open mine shaft in the northerly area is a hazard to livestock, wildlife, and humans. A barren area near the shaft had radioactivity of 582

This report discusses the Isabella South and Isabella North. The Isabella North is on Navajo allotment (surface and mineral) and is being handled by Region 9.

cps, while 330 cps was measured at the shaft opening. The former roadway that cuts through this area has been extensively incised by erosion. Contamination of vicinity soils and surface drainages by precipitative erosion and wind dispersion comprise the primary contaminant pathways that may be associated with this site. Additionally, site runoff of contaminated wastes may impact ground water quality either through seepage through alluvium or by direct entry to the subsurface via the open hole and shaft.

**Targets:** Residences are located near the junction of State Hwy. 605 and 509, approximately 3.0 air-miles southeast of the Site. Other potential targets may include cattle and wildlife.

Closest well sampled to date: livestock well SMC-17 (0.8 air-miles; 98.4 µg/l total uranium in 2009 sampling).

**Site ownership and Potentially Responsible Parties:** Surface rights reportedly are held by the Bureau of Land Management (BLM); mineral rights are held by Newmont Mining Company. United Nuclear and Ranchers Exploration Company reportedly last operated the mine.

**File review:** NMED staff reviewed the following files:

- Database compiled by Mining and Minerals Division of the New Mexico Energy and Natural Resources Department (07/20/2007).
- Anderson, Orin J., 1980. "Abandoned or inactive uranium mines in New Mexico."
- McLemore, Virginia T. and William L. Chenoweth, 1991. "Uranium mines and the Grants district, Cibola and McKinley Counties, New Mexico." New Mexico Mines and Mineral Resources Open-file report 353.
- Rappaport, Linda, "Uranium deposits of the Poison Canyon ore trend, Grants District." "Geology and technology of the Grants Uranium Region, 1963. State Bureau of Mines and Mineral Resources.
- U.S. Geological Survey, 1997. "Gallup quadrangle NURE HSSR study." OFR-97-492.

**Site reconnaissance:** NMED staff conducted a Site reconnaissance on July 2, 2009.

**Recommendation:** A release of CERCLA hazardous substances has been documented at the site. NMED recommends further investigation under CERCLA to assess the risk posed by the site using the Hazard Ranking System.

NMED recommends that the investigation include the following:

1. Sample sediments along drainages to characterize extent of Site-derived waste dispersion.
2. Investigate and characterize ground water impacts.

In addition NMED recommends the following actions be performed to address immediate threats to public health and the environment:

1. Remove waste with elevated radioactivity.
2. Plug open shafts.

Southern portion

Northern portion is Navajo allottee surface and mineral.



**Figure 1: Isabella Mine overview**





**Figure 2: Isabella Mine, southern part—measurements taken on July 2, 2009**

“Px” reference the location of photographs on pages following.





**Figure 3: Isabella Mine, northern part—measurements taken on July 2, 2009**

"Px" reference the location of photographs on pages following.





P1: Isabella Mine vent shaft



P2: Isabella mine barren area



P3: Isabella Mine waste pile



P4: Isabella Mine shaft

Ms. LaDonna Turner, EPA Region 6 Site Assessment Manager  
Pre-CERCLIS Screening Assessment of Isabella Mine, McKinley County, New Mexico  
September 10, 2009



P5: Barren waste pile